



Nothing but **HEAVY DUTY.**™



M18 BP

User Manual

操作指南

操作指南

사용시 주의사항

คู่มือการใช้

Buku Petunjuk Pengguna



8










13








8






7


























A AS 2-250	4931 4472 95
B AS 300 / 500	4931 4472 94





START
STOP
V



Insulated gripping surface



絕緣的握持表面

绝缘的握持表面




절연 그립 표면

พื้นผิวจับกันความร้อน

Permukaan genggam berinsulasi

















START
STOP
✓






**START
STOP**
▼








VII

