



Nothing but **HEAVY DUTY.**[™]



M18 FCHS

User Manual

操作指南

操作指南


사용시 주의사항






คู่มือการใช้

Buku Petunjuk Pengguna




11





Accessory
配件
配件
액세서리
อุปกรณ์เสริม
Akseori






1

2



3


4



16

17





13











14











15






18

















Insulated gripping surface

絕緣夾持表面

絶縁夾持表面



절연 그립 표면

ดำเนินการทดสอบการตัด

Lakukan tes pemotongan



Start



Carry out a test cut

進行測試

进行测试

시험 절단을 수행하십시오.








พื้นผิวจับกันความร้อน





Permukaan genggam berinsulasi











Stop
























1.




2.




3.






4.



VIII

5.

A



5.

B

